







INSTRUCTION MANUAL




A	B	C	D	E
				
x4	x45	x45	$\Phi 3.5 \times 14 \text{ mm}$ x33	x1
F	K	L	M	
				
$\Phi 4 \times 20 \text{ mm}$ x4	$\Phi 5 \times 50 \text{ mm}$ x2	$\Phi 8 \text{ mm}$ x2	x2	
















3





4





5



6



7



8

<i>D</i>	<i>K</i>	<i>L</i>	<i>M</i>	
				
Φ3.5×14mm x16	Φ5×50mm x2	Φ8mm x2	x2	

