

# P858 Leg Press & Hack Squat cover




# P858Leg Press & Hack Squat general assembly drawing





| NO | PN | PCS |
|---|---|---|
| 1 | P858-01 Left welding group of bracket | 1 |
| 2 | P858-02 Right welding group of bracket | 1 |
| 3 | P858-03 Connect support welding group | 2 |
| 4 | P858-04 Lower support welding group | 1 |
| 5 | P858-05 Sliding welding group | 1 |
| 6 | P858-06 Backrest welding group | 1 |
| 7 | P858-07 Locate the left welding group | 1 |
| 8 | P858-08 Locate the right welding group | 1 |
| 9 | P858-09 Rotary shaft sleeve welding group | 2 |
| 10 | P858-10 Lower back welding group | 1 |
| 11 | P858-11 Seat support welding group | 1 |
| 12 | P858-12 Seat cushion adjustment welding group | 1 |
| 13 | P858-13 Insurance welding group | 2 |
| 14 | P858-14 Seat pad fixed welding group | 1 |
| 15 | P858-15 Weight matching rod welding group | 2 |
| 16 | P858-0007 Square cushion | 1 |
| 17 | P858-0008 Seat pad fixed board | 1 |
| 18 | P858-0009 Galvanized connection shaft1 | 1 |
| 19 | P858-0010 Galvanized connection shaft2 | 1 |
| 20 | P858-0011Stainless steel barbell rod | 1 |
| 21 | BQ-5002 φ40 shock pad | 4 |
| 22 | X102 protective pad | 4 |
| 23 | HM-6004 50Round tube plug | 4 |
| 24 | P858-0012 backplate | 2 |
| 25 | P858-0014 Stainless steel short barbell bar | 1 |
| 26 | P858-0015ray axis | 2 |
| 27 | BQ-5001 Cover shock absorber pad | 2 |
| 28 | Large gasket | 4 |
| 29 | External hexagonal screw M10X130Half teeth | 1 |
| 30 | External hexagonal screw M10X120 半牙 | 20 |
| 31 | 外六角螺钉 M10X110 Half teeth | 1 |
| 32 | External hexagonal screw M10X95 Half teeth | 1 |
| 33 | External hexagonal screw M10X75 | 6 |
| 34 | External hexagonal screw M10X20 | 6 |
| 35 | hexagon headed bolt M8x25 | 4 |
| 36 | Inner hexagon cylindrical head screw M10X20 | 2 |
| 37 | Cross slot head screw M5x8 | 20 |
| 38 | locknut M10 | 29 |
| 39 | plain washer Φ10 | 60 |
| 40 | plain washer Φ8 | 4 |

# P858-01Left welding group of bracket





| NO | PN | PCS |
|---|---|---|
| 1 | P858-01 Support left welding parts group | 1 |
| 2 | P858-0001 Nylon set | 2 |
| 3 | X165 Rectangular floor mat | 2 |
| 4 | HM-5010 Square pipe plug 50x100 | 1 |
| 5 | Inner hexagon head screwM10x25 | 2 |

# P858-02Right welding group of bracket





| NO | PN | PCS |
|---|---|---|
| 1 | P858-02 Support right welding parts group | 1 |
| 2 | P858-0001 Nylon set | 2 |
| 3 | HM-5010 Square pipe plug 50x100 | 1 |
| 4 | X165 Rectangular floor mat | 2 |
| 5 | Inner hexagon head screw M10x25 | 2 |

# P858-03Connect support welding group




| NO | PN | PCS |
|---|---|---|
| 1 | P858-03 Connect support welding parts group | 2 |

# P858-04Lower support welding group





| NO | PN | PCS |
|---|---|---|
| 1 | P858-04<br>Undersupport welding parts group | 1 |
| 2 | X165<br>Rectangular floor mat | 1 |
| 3 | P858-0001<br>Nylon set | 2 |
| 4 | HM-5010<br>Square pipe plug 50x100 | 1 |
| 5 | Inner hexagon head screw<br>M10x25 | 1 |

# P858-05Sliding welding group





| NO | PN | PCS |
|---|---|---|
| 1 | P858-05 Sliding welding parts group | 1 |
| 2 | P858-0002 Pull pin (galvanization) | 1 |
| 3 | P858-0003 headrest | 1 |
| 4 | P858-0005 Shoulder pad left | 1 |
| 5 | P858-0013 Shoulder pad right | 1 |
| 6 | HM-5012Square pipe plug 50x50 | 7 |
| 7 | linear bearing LM40 | 4 |
| 8 | φ60 inside callipers | 4 |
| 9 | HM-5018 Pull pin cap | 1 |
| 10 | HM-5017 spring (galvanization) | 1 |
| 11 | HM-5015 Round floor mat | 2 |
| 12 | HM-5057 star wheel M8 match Φ20hole | 2 |
| 13 | P858 Tear not rotten2 | 2 |
| 14 | 5A set of tail | 2 |
| 15 | 5The front part of the cover | 2 |
| 16 | hexagon headed bolt M8x75 | 4 |
| 17 | hexagon headed bolt M8x25 | 3 |
| 18 | Inner hexagonal flat head tight set nail M8x8 | 2 |
| 19 | plain washer Φ8 | 7 |
| 20 | Inner hexagon cylindrical head screw M10X20 | 2 |
| 21 | Inner hexagon head screw M8x25 | 2 |

# P858-06Backrest welding group





| NO | PN | PCS |
|---|---|---|
| 1 | P858-06 Backrest welding parts group | 1 |
| 2 | P858-0004 Back cushion | 1 |
| 3 | P858-0016Nylon set | 2 |
| 4 | Inner hexagon head screwM8x25 | 4 |

# P858-07Locate the left welding group





| NO | PN | PCS |
|---|---|---|
| 1 | P858-07 Locate the left welding parts group | 1 |
| 2 | Inner hexagonal flat head tight set nail M8x8 | 1 |

# P858-08Locate the right welding group





| NO | PN | PCS |
|---|---|---|
| 1 | P858-08 Locate right welding parts group | 1 |
| 2 | Inner hexagonal flat head tight set nail M8x8 | 1 |

# P858-09Rotary shaft sleeve welding group





| NO | PN | PCS |
|---|---|---|
| 1 | P858-09 Rotary shaft sleeve welding parts group | 2 |
| 2 | P858-0001 Nylon set | 4 |

# P858-10Lower back welding group





| NO | PN | PCS |
|---|---|---|
| 1 | P858-10 Lower back welding parts group | 1 |
| 2 | P858-0006 Lower back cushion | 1 |
| 3 | Inner hexagon head screw M8x25 | 4 |

# P858-11Seat support welding group





| NO | PN | PCS |
|---|---|---|
| 1 | P858-11 Pcushion support welding set | 1 |
| 2 | F3-3009Resignation pull pin mother | 1 |
| 3 | F3-3011 return spring | 1 |
| 4 | F10-5011 Reset pull pin shaft | 1 |
| 5 | HM-5054 60changed50drill holder | 1 |
| 6 | HM-5018 Pull pin cap | 1 |
| 7 | hexagon headed bolt M8x20 | 1 |

# P858-12Seat cushion adjustment welding group




| NO | PN | PCS |
|---|---|---|
| 1 | P858-12 Pcushion adjusting welding set | 1 |

# P858-13Insurance welding group





| NO | PN | PCS |
|---|---|---|
| 1 | P858-13 Insurance welding parts group | 2 |
| 2 | F3-3003 Anti-collision column | 6 |
| 3 | 5A set of tail | 4 |
| 4 | P858Tear not rotten1 | 4 |
| 5 | HM-5057 star wheel M8 match Φ20hole | 4 |
| 6 | 5The front part of the cover | 4 |
| 7 | Inner hexagon head screw M5x12 | 6 |
| 8 | Inner hexagon head screw M8x25 | 4 |

# P858-14Seat pad fixed welding group




| NO | PN | PCS |
|---|---|---|
| 1 | P858-14 Set of cushion fixed welding | 1 |
| 2 | HM-5012 Square pipe plug 50x50 | 2 |
| 3 | HM17-2002 Flying bird nylon sleeve | 2 |
| 4 | S1643Small pad board (Hard polyurethane) | 1 |
| 5 | Inner hexagonal flat head tight set nail M8x12 | 2 |
| 6 | Inner hexagon head screw M6x12 | 2 |

# P858-15Weight matching rod welding group




| NO | PN | PCS |
|---|---|---|
| 1 | P858-15 Wiring rod welding parts group | 2 |
| 2 | HM-5081 Round tube plugΦ30 | 2 |